

Assembly tool - PSM-HCS-KONFTOOL - 2799526

Please be informed that the data shown in this PDF Document is generated from our Online Catalog. Please find the complete data in the user's documentation. Our General Terms of Use for Downloads are valid (<http://download.phoenixcontact.com>)



HCS assembly kit for F-SMA quick mounting connectors, including stripping blade, stripping pliers, aramide yarn scissors, fiber stripper, microscope, fiber cleaving tool for standard HCS fibers, and documentation

Key commercial data

Packing unit	1
Minimum order quantity	1
Catalog page	Page 539 (IF-2011)
GTIN	 4 017918 148669
Custom tariff number	82060000
Country of origin	GERMANY

Technical data

Product type	Assembly tool
Approval	GOST

Classifications

ETIM

ETIM 2.0	EC001476
ETIM 3.0	EC001476
ETIM 4.0	EC002609
ETIM 5.0	EC002609

UNSPSC

UNSPSC 11	26121607
UNSPSC 12.01	26121607
UNSPSC 13.2	26121607
UNSPSC 6.01	26121607
UNSPSC 7.0901	26121607

eCl@ss

eCl@ss 4.0	27061001
eCl@ss 4.1	27061001

Assembly tool - PSM-HCS-KONFTOOL - 2799526

Classifications

eCl@ss

eCl@ss 5.0	27061803
eCl@ss 5.1	27061803
eCl@ss 6.0	27061803
eCl@ss 7.0	27061803

Approvals

Approvals

Approvals

GOST

Ex Approvals

Approvals submitted

Approval details

GOST



Accessories

Accessories

Cable/conductor

FO cable - PSM-LWL-HCS-RUGGED-200/230 - 2799885



HCS cable, duplex 200/230 µm, by the meter, without connector, for indoor installation

FO cable - PSM-LWL-HCSO-200/230 - 2799445



HCS cable, duplex 200/230 µm, by the meter, without connector, for outdoor installation

Assembly tool - PSM-HCS-KONFTOOL - 2799526

Accessories

Plug/Adapter

FO plug connectors - PSM-SET-FSMA/4-HCS - 2799487



F-SMA plug set for HCS fiber, for self assembly consisting of 4 quick mounting connectors with bend protection sleeve

Tools

Assembly tool - PSM-HCS-CLEAVETOOL - 2744995



Fiber cleaving tool for HCS fibers, pin assignment: F-SMA for the assembly of F-SMA quick mounting connectors, supplements PSM-HCS-KONFTOOL...

Assembly tool - PSM-HCS-CLEAVETOOL/B-FOC - 2708478



Fiber cleaving tool for HCS fibers, pin assignment: B-FOC (ST) for the assembly of B-FOC quick mounting connectors, supplements PSM-HCS-KONFTOOL...

Assembly tool - PSM-HCS-CLEAVETOOL/SCRJ - 2313122



Fiber cleaving tool for HCS fibers, pin assignment: SCRJ or SC duplex for the assembly of SC quick mounting connectors, supplements PSM-HCS-KONFTOOL...

Stripping tool - PSM-FO-STRIP - 2744199



Stripping pliers for transmitting individual elements of the fiber optic cable. Especially suited for all polymer and HCS cables. Special mechanics and precise blade form avoid damage to the fiber optic fibers. Dimensions: (L x W x H) 160 x 130 x 36 mm.

Assembly tool - PSM-HCS-KONFTOOL - 2799526

Accessories

FO accessories - PSM-ARAMID-CUTTER - 2744872



Aramid scissors. Extremely sharp and rugged scissors with serrated edge for shortening aramid yarn, supporting elements, and other materials. Dimensions: (L x W x H) 165 x 80 x 12 mm, blade length: 42 mm.

FO accessories - PSM-FO-COATING-STRIP 0.3MM - 2744885



Optical fiber stripping tool. Tool for removing the primary coating of the optical fiber. Dimensions: (L x W x H) 98 x 45 x 13 mm.

FO accessories - PSM-HCS-MICROSCOPE 100X - 2744898



Microscope for visual checks following connector assembly.. 100x zoom, with light. Can be used with two different adapters for F-SMA/B-FOC (ST[®])/SCRJ/SC duplex connectors. Dimensions: (L x W x H) 148 x 44 x 23 mm

Measuring instrument - PSM-FO-POWERMETER - 2799539



Fiber optic measuring case, consisting of an optical power meter, F-SMA, B-FOC adapters, reference fibers and operating instructions

Stripping tool - WIREFOX-D 16 - 1212173



Stripping tool, for stripping lines (specially for fiber optics lines) of Ø 4 - 16 mm

单击下面可查看定价，库存，交付和生命周期等信息

[>>Phoenix Contact\(菲尼克斯\)](#)