



| REVISIONS | | | |
|-----------|-------------|----------|----------|
| REV | DESCRIPTION | DATE | APPROVED |
| 012 | REVISED | 02/23/95 | JAD |

| | | | | | |
|--|---------------------|----------|--------|-----------|--|
| UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCE ON | DRAWN BY | N.K. | DATE | 10-29-86 | AMP Incorporated 140 Fourth Avenue Waltham, MA 02451-7599 |
| | CHECKED BY | J. Jones | DATE | 10-31-86 | |
| FRAC. DEC. ANGLES | APPD BY | E.R.S. | DATE | 10-31-86 | AMP TITLE OSM 4 HOLE FLANGE MOUNT JACK RECEPTACLE - FIELD REPLACEABLE SIZE B CODE IDENT NO. 26805 2052-3351-02 REV 012 SCALE 5:1 SHEET 1 OF 1 |
| ± 1/64 ±.005 ± ° | USE ASS'Y PROCEDURE | NO. AP. | 20-735 | 408-04862 | |

CUSTOMER DRAWING AMP PART # 1052624-1 SHEET 1 OF 1 REV A

单击下面可查看定价，库存，交付和生命周期等信息

[>>TE Connectivity\(泰科\)](#)